



1/6




Figure 1

2/6




Figure 2




Figure 3 Schematic of laboratory wastewater treatment system.

4/6




Figure 4 . Schematic of the RO membrane separation test unit.

5/6




Figure 5. Feed inlet pressure and permeate temperature at different volume reductions

6/6




Figure 6. Permeate flow rate and electric conductivity at different volume reductions (PFR -- permeate flow rate, PEC -- permeate electric conductivity, AG -- AG2540, SE -- SE2540)





FIGURE 1

FIGURE 2



Schematic of laboratory wastewater treatment system.

FIGURE 3




Figure 4 . Schematic of the RO membrane separation test unit.

*All numbering
and labeling
formalized*

Enlarged and figures separated to 2 sheets




Figure 5. Feed inlet pressure and permeate temperature at different volume reductions




Figure 6. Permeate flow rate and electric conductivity at different volume reductions (PFR - permeate flow rate, PEC - permeate electric conductivity, AG - AG2540, SE - SE2540)

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.